

MMT-8007 - DIGITAL ALARM-THERMOMETER WITH PROBE

SPECIFICATION

- Measuring temperature range:
 - External probe Temperature Range: -50~+70 °C/-58~+158 °F
 - Internal sensor Temperature Range: 0~+50 °C/+32~+122 °F
- Temperature accuracy: ±1°C (±2°F)
- Temperature display resolution: 0.1°C (0.1°F)
- MAX/MIN temperature memory records
- Operating voltage: 1.5V, 1 PCS AAA battery
- Total Dimension: 110mm*70mm*19.5mm
- Net weight: pprox.82g

FEATURES

- LCD screen shows indoor & outdoor temperature.
- Preset alert temperature.
- Stand for shelf or hanging hole at back.
- Max/Min temperature memory records.
- The MMT-8007 has 2 channels:
 - The top display labelled "IN" is the internal sensor in the display
 - The bottom display labelled "OUT" is the external wired sensor

BUTTONS & OPERATIONS

1.MIN/MAX

- Press MIN/MAX key to display the maximum IN/OUT (Internal/Probe) temperature.
- Press MIN/MAX key again to display the minimum IN/OUT (Internal/Probe) temperature

2.RESET does the following:

- Press once to reset max and min to current temperature.
- Press twice to reset alert temperature range to default of -1°C~4°C

3.ALERT SET is used to:

- Turn on/off ALERT
- Holding 1 second for setting alert temperature range

4.°C/°F & ADJ


- Adding one deg C press once or auto advanced (-50~70) when holding the key down under ALERT SET mode.
- Select °C or °F Display

ALERT SET





Applies to External Probe


HOLDING 1 SECOND FOR SETTING ALERT TEMPERATURE RANGE to see default setting Press once to adjust "OUT" (MAX) limit




PRESS ONCE ADDING ONE DEG C OR AUTO ADVANCED (-50~+70) WHEN HOLDING THE KEY



HOLDING THE KEY will advance temperature rapidly




Press 2X to adjust "IN" (MIN) limit




HOLDING THE KEY






Buzzer on 5 seconds and off 55 seconds when the Outdoor Temp. between (+24degC~ +26degC.)




HOLDING 1 SECOND FOR SETTING ALERT





HOLDING THE KEY



Buzzer on 5 seconds and off 55 seconds when the Outdoor Temp.<26degC or> 28degC



TURN OFF ALERT



TURN ON ALERT

